

C-17 Depot Partnering Meeting

Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)

Group Leader: Rebecca Denn, HQ AFMC/LGIA

Unless otherwise noted, all interfaces depicted between D035K and C-ICP will flow through M024B and DAAS. Transmission between DAAS and C-ICP could include feed to Data Exchange or flow through Data Exchange.

DAAS and M024B may need to be modified to transmit transactions that do not currently pass through those systems.

Processes that currently exist are noted by solid lines. -----


Future processes yet to be developed are noted by dashed lines.

Physical movement of material is noted by dotted lines.

**C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA**

Logistics Reassignment (Decap/cap - changing stock fund)

Chart depicts Losing IM = AF-ICP; Gaining IM = C-ICP.
If LIM = C-ICP and GIM = AF-ICP, same actions should occur.




* DZC not transmitted to DSS for AF balances at ALCs (AF Single Owner logic)

- Transfer all condition codes (except condition L?)
- Do not transfer backorders with BV and BZ status

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

RIMCS/Retrograde



- Change D035K BDR logic to try to find geographically closest repair site and load to SRA field (for all ICPs).
- If D043 can pass RIMCS changes daily, C-ICP and AF-ICP could push only one repair site and change as needed.
- Provide capability to change (override) RIMCS in SBSS and D035K.

**C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA**

Receipt/Induction of End Item at SOR (ALC)

Contractor DoDAAcs:


EDxxxx = ICP

EBxxxx = storage site

EZxxxx = repair site

XXXXX = repair site
EYXXXX = production site

**“TXXXXX” = production site
“MOB” = main operating base**




- Short-term: 206 can pull out of storage or can load Maint Express table
- D035K feed to EXPRESS system: Should C-ICP data be included or excluded?
- D035 needs modification to allow multiple DoDAACs for each C-ICP routing identifier.
- Each C-ICP needs TAC assigned for movement of material; TAC assign logic required in DSS.
- Use VIP to store multiple SOR locations? Create way to update RAMP/SBSS at same time

(Concurrent changes to RAMP/D035K interface?)

updated

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Receipt from Depot Maintenance (serviceable turn-in) and Material Disposition



•Three options for material disposition:

- If ZR processed prior to turn-in, ship with A2- based on ZR data; else
- If C-ICP default location loaded, ship to default location (new logic to D035K); else
- Stow in DLA warehouse.

* ZR- transaction can also be loaded into D035K via EXPRESS/D035A and manually via D035K RQIE panel.

- A2, D7-, AR-, and DW- resulting from pre-positioned ZR- will contain customer or C-ICP doc nr.
- Y5 (internal to D035K), D7-, AR-, and DW- resulting from auto ship to default C-ICP location will contain D035K FB20xx doc nr.
- DAC transactions will have Depot Maintenance document number from turn-in transaction.
- Change to C-ICP GOLD system to recognize ALCs ('F-B') as storage sites.

C-17 Depot Partnering Meeting

Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)


Group Leader: Rebecca Denn, HQ AFMC/LGIA

Condemnation determination

Maintenance repair - Item condemned

Depot Maintenance must contact C-ICP (preferably electronically to GOLD - status "held for scrap approval")

- Depot Maintenance explain why
- Provide pictures
- Use 202 process (within AF, this goes to ES or engineering)
 - 202 process can be done electronically
 - Workflow manager process
 - Response disposition block (electronic)
 - Attach DSO change




* A5- to DSS is result of Y5- processed internally in D035K

Questions/issues:

- Need to address firewalls
- How will Depot Maintenance know SOS is C-ICP? SOS is not in G402A system.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Issue and shipment confirmations




For any issue or shipment that is not a ship-to-disposal, the confirmation from DSS will be an AR0, ARA, or ARB.

For a shipment to disposal, the confirmation will be an ARJ, ARK, or ARL.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Usage data to C-ICP (D200 info)
Reparable Items




Verify C-ICP will not receive duplicate usage data for SBSS and D035K.


C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

**Ordering C-ICP managed bits/pieces
(Budget code S)**

1. Establish stock level




2. Order/receive item



- C-ICP may follow-up to D035K with DRF transaction.
- D035K reply to follow-up is DRB transaction.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Contractor ICP-managed assets in excess of Depot Retail requirements




Depot Retail-owned assets that are in excess of requirements and are Contractor-managed will be reported and managed using the MILSTRIP materiel returns process.

D035K logic will be modified to always act on the status returned from the C-ICP. (Retail item manager will not be allowed to decide whether to return items for which credit is not being given, or whether to dispose of items the C-ICP directs to not be returned).


C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Contract Receipt for C-ICP Source of Supply at ALC



C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Asset balance adjustments




- D8- and D9- transactions can result from inventory, book-to-book, asset reconciliation, denial, and reidentification processes in DSS. They can also be generated from Depot Maintenance or input via D035K screens.
- DAC (condition transfers) can be generated from DSS.
- Adjustments originating from DSS will have DSS document numbers.
- Pecking order for adjustments
- Request Inventory Report of Survey

Action Item for Air Staff to meet with OSD and DDC on inventory integrity.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Issue/Shipment denials and associated balance adjustments




The A6- and D9- transactions will all have the same stock number, document number, and suffix as the shipment transaction.

The C-ICP may need to generate additional D9-(s) to drop the remaining asset balances (according to denial management code).

The denial of the A5E issue occurs prior to actual materiel delivery and receipt acknowledgement from Depot Maintenance; that is why no DAC is transmitted to C-ICP in the above process.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

**Packaging, Transportation, and Regulated Materiel
(PT&RM)**



C-17 Depot Partnering Meeting


Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)

Group Leader: Rebecca Denn, HQ AFMC/LGIA

- Additional Reversal Transactions

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Reversal of receipt (C-ICP asset) and associated issues/shipments




Complete receipt process without reversal depicted on other charts.

The A5E issue reversal occurs prior to actual materiel delivery and receipt acknowledgement from Depot Maintenance; that is why no DAC is transmitted to C-ICP in the above process.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Reversal of Depot Supply requisitioned receipt (C-ICP managed bit/piece)




Complete requisitioned receipt process without reversal depicted on other chart.

DRA reversal shown as flow #4 is not a MILS transaction, but will be used to notify the C-ICP of a receipt reversal so the due-in for depot retail can be re-established. The reversal quantity could be less than the original receipt quantity.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA


Depot maintenance turn-in and turn-in reversal (DIOH)



Complete maintenance turn-in process without reversal depicted on other charts.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA


Depot maintenance turn-in and turn-in reversal (non-DIOH)



Complete maintenance turn-in process without reversal depicted on other charts.
 For non-DIOH turn-ins, a depot maintenance turn-in transaction (non-MILS format) will be passed to the C-ICP in lieu of the DAC transaction.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Non-DIOH Issues to depot maintenance



For non-DIOH issues, a depot maintenance D7- transaction (non-MILS format) will be passed to the C-ICP in lieu of the DAC transaction.

C-17 Depot Partnering Meeting
Receiving/Packaging/Shipping Group Flows (5-6 Mar 03)
Group Leader: Rebecca Denn, HQ AFMC/LGIA

Shipment cancellations (C-ICP-managed wholesale assets)

